## Hertfordshire County Scout Council Phasels Wood Activity Centre Fire Risk Assessment



1 Building - Jubilee Hut

**Designated use -** Indoor hall and kitchen area.

**Approximate size –** 6m x 12m

**Number of beds –** N/A Non sleeping accommodation

**Number of floors –** Single storey

**Roof construction –** Metal sheeting on timber frame

Walls - Mixture of concrete block and timber frame all wood clad

**Internal linings-** Mixture of fiberboard and timber

**Floors** – Concrete painted with epoxy resin

**Means of escape –** Via fire exit doors (it is understood that whenever the premises are occupied no exit door is secured in such a manner that it is not easily and immediately openable)

**Fire Fighting equipment –** 1 x CO2, 1 x WATER type extinguishers. 1 x fire blanket

Fire Alarm system – N/A

**Heating/hot water/cooking –** Double natural gas cooker.

Gas shut off valve at side of building

**Electrical installation -** 240-volt supply throughout. Fuse board fitted in main hall of building

General Lighting - 240-volt supply throughout

**Emergency Lighting –** Non maintained throughout

**Signs and Notices –** All to current standards

**Furnishings –** Only fire-retardant furnishings as fitted in buildings are permitted.

## 2 Personnel Involved Instructors/Staff/Campers/Visitors Number of people 1 – 100

3	Potential Hazards 4		4	Risk Level
	1	Waste		Low
	2	Doors		Low
	3	Smoking		Low
	4	Cleaning Equipment and chemicals		Low
	5	Gas equipment & boilers		Low
	6	Electrical equipment		Low
	7	Cooking		Low

## 5 Measures Taken to Control Hazards

- Ensure floor area kept clear, combustible material tidied away and waste bins cleared regularly
- 2 Ensure doors are unlocked whilst building is in use. Approved BS signage fitted
- 3 Signs and ask people not to smoke indoors.
- Store cleaning materials in designated areas, chemicals secured, COSHH and product specific training as appropriate. Remove industrial/flammable chemicals from buildings.
- 5 Appropriate service and testing regime, keep clear of combustible materials
- Use as per manufacturers instructions, PAT regime in place, minimise trailing cables, do not overload fuses, appropriate trips on circuits
- 7 Ensure cookers are never left unattended when on.

NOTE - Extinguishers are present and tested yearly. All occupiers are supplied "Fire Action" information prior to arrival and should understand what to do in the case of an emergency.